

### 6.3.5 REPORTING

Report routine conductivity measurements to three significant figures, whole numbers only, in microsiemens per centimeter at 25°C.

- ▶ Record the accuracy range of the instrument system in the data base, if possible, and always report it with published values.
- ▶ Enter field-determined conductivity measurements on NWQL Analytical Services Request form using the correct parameter code.